

EXHIBIT C

EXHIBIT C-1

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A				City: IGO	County: SH	Directions: W/ON PLACER RD>W/ON SOUTH FORK RD>N/ON ZOGG MINE RD TO END				Inspector / Company: CNU			
Division: North Valley	Circuit: GIRVAN 1101	SSD #: 6091	SSD Rte #: 50	Routing #: 2191	(none):		Area:	SRA No	Alerts: AX				
Insp Date / Time: 4/28/2015 3:49:30 PM		Tag Type: Unforeseen	Tag Number: 4/28/2015	Line Name:		Pole Num:	Quad Map:	Removal #:	Customer Name/Phone:				
Comment: EP @ PSTD ADD @ END OF RD, P27 2 S/W/OF OF EP ON HILL (NARROW RD & VERY SMALL TA) I SPOKE WITH OWNER OF AND ITS NOT HIS PROPERTY, NICE GUY													
									<u>Audit</u>		<i>Last Edit: 4/29/2015 7:02:01 AM by:</i>		
Tree Number 1	Tree Species: Douglas Fir	Crew: CA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 80 17	Clearance Prox: 15 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Trim B	Account: M	Wire Conditions:	Insp Date: 4/28/2015 3: PM
	Comment: @ P27 (REMOVE DEAD TOP)					Notification: OK		Work Request: SHNV1021502		WC Date: 4/30/2015	WC Qty: 1	WC Trim: FAB	C mpleted By: BA (104)
	Lat/Long: 40.542336667, -122.585291667 <u>Google Map!</u>				External TreeID:						<u>Audit</u>		Last Edit: 4/28/2015 by:
	Rx Comment:												

EXHIBIT C-2

Search **Print****North Valley Division - Distribution (RT - 2015)****Work Request:** SHNV1021502**Contractor:** Davey Tree- Sent to Contractor.**Date Issued:** 4/29/2015 11:52:49 AM**Completed:** 4/30/2015 **By:** [REDACTED]

Circuit: GIRVAN 1101 - (0103401101)

1.) 1 FP-Tr 1 FP-Tr (TM) 4/30/15 **By:** [REDACTED] r *Invoiced***Units Assigned: 1.0****Units Completed: 1.0 - (100.0%)**

! - Indicates that some of the work completed is different than what was assigned.
 r - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 3/2/2021 8:51:16 AM.

EXHIBIT C-3

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A		City: IGO		County: SH		Directions: W/ON PLACER RD>W/ON SOUTH FORK RD>N/ON ZOGG MINE RD;LAST HSE@END/OF RD		Company:				
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 6091	SSD Rte #: 606060	Routing #: 100	(none):	Area:	SRA Yes	Alerts: PI RP				
Insp Date / Time: 4/5/2017 10:26:21 AM	Tag Type:	Tag Number:	Line Name:		Pole Num:	Quad Map:	Removal #: 3874698	Customer Name/Phone:				
Comment: EP @HSE @END/OF ZOGG MINE RD												
								Audit				
								Last Edit 4/6/2017 2 36 42 PM by				
Tree Number 1	Tree Species: Douglas Fir	Crew: LA	Priority: Routine	TGR: No	Owned By: Private	Height DBH Clearance Prox: 105 21 99 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Rmv2 B	Account: E	Wire Conditions:	Insp Date: 4/5/2017 10:40:02 AM
	Comment: .9S/E/OF EP. DEAD 92' OFF S/SD/LNS @RD				Notification: OK	Work Request: CENV1000574		WC Date: 4/12/2017	WC Qty: 1	WC Trim: F2B	Completed By:	Invoice: B2 (104)
	Lat/Long: 40.54244, -122.585915 Google Map			External TreeID:						Audit		Last Edit: 4/6/2017 2 36 42 PM by
	Rx Comment: DROP & LEAVE TREE WHOLE ON S/SD/OF RD											

EXHIBIT C-4

Search **Print**

North Valley Division - Distribution (CM - 153400)

Work Request: CENV1000574

Contractor: Davey Tree- Sent to Contractor. **Order No:** 8176578

Date Issued: 4/10/2017 8:06:00 AM

Completed: 4/12/2017 By: [REDACTED]



Circuit: GIRVAN 1101 - (0103401101)

1.) 1 FP-R2 1 FP-R2 4/12/17 By: [REDACTED] r Invoiced

Units Assigned: 1.0

Units Completed: 1.0 - (100.0%)

! - Indicates that some of the work completed is different than what was assigned.
r - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 11/3/2020 3:58:04 PM.

EXHIBIT C-5

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A			City: IGO		County: SH	Directions: W/ON PLACER>W/ON SOUTH FORK RD> N/ON ZOGG MINE RD				Inspector / Company: [REDACTED] - CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 6091	SSD Rte #: 50	Routing #: 3	(none):	Area:	SRA Yes	Alerts: DG					
Insp Date / Time: 4/5/2017 10:54:26 AM	Tag Type: Unforeseen	Tag Number: 040517	Line Name:			Pole Num:	Quad Map:	Removal #:	Name/Phone: [REDACTED]				
Comment: EP (NEW) @LAST HSE @END\OF ZOGG MINE RD													
									Audit		Last Edit: 10/23/2018 1:35:22 PM by: [REDACTED]		
Tree Number 1	Tree Species: Cedar	Crew: LA	Priority: Accelerate	TGR: No	Owned By: Private	Height DBH: 40 15	Clearance Prox: 9 Inside	Cycle: Rtn	Qty: 2	Trim Type: Side	Account: M	Wire Conditions:	Insp Date: 4/5/2017 11:00:42 AM
	Comment: .1-.2S/E/OF EP N/SD/RD 3.5'-4' OUT.					Notification: OK	Work Request: SHNV1023721		WC Date: 4/12/2017	WC Qty: 2	WC Trim: SD	Completed By: [REDACTED]	Invoice: TR (104)
	Lat/Long: 40.542536667, -122.586531667 Google Map!				External TreeID:						Audit	Last Edit: 4/5/2017 by: [REDACTED]	
	Rx Comment: NEW EP & CROSSARM. TREES AVGH&DBH												

EXHIBIT C-6

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A			City: IGO		County: SH	Directions: W/ON PLACER>W/ON SOUTH FORK RD> N/ON ZOGG MINE RD				Inspector / Company: [REDACTED] - CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 6091	SSD Rte #: 50	Routing #: 5	(none):		Area:	SRA Yes	Alerts: DG				
Insp Date / Time: 4/5/2017 11:10:47 AM	Tag Type: Unforeseen	Tag Number: 040517	Line Name:			Pole Num:	Quad Map:	Removal #:	Name/Phone: [REDACTED]				
Comment: EP @LAST HSE @END\OF ZOGG MINE RD (NEW EP & CROSSARM)													
									Audit		Last Edit: 10/23/2018 1:35:31 PM by: [REDACTED]		
Tree Number 1	Tree Species: Canyon Live Oak	Crew: LA	Priority: Accelerate	TGR: No	Owned By: Private	Height DBH: 40 20	Clearance Prox: 10 Inside	Cycle: Rtn	Qty: 2	Trim Type: Side	Account: M	Wire Conditions:	Insp Date: ([REDACTED]) 4/5/2017 11:12:13 AM
	Comment: .3-.5S/E/OF EP 3.5-4' OUT S/LNS BOTH/SDS/RD					Notification: OK	Work Request: SHNV1023721		WC Date: 4/12/2017	WC Qty: 2	WC Trim: SD	Completed By: [REDACTED]	Invoice: TR (104)
	Lat/Long: 40.54254, -122.586111667 Google Map!				External TreeID:						Audit	Last Edit: 4/5/2017 by: [REDACTED]	
	Rx Comment: (NEW EP & CROSSARM) TREES BOTH SDS/RD(1 FLAGGED W/MOSS). AVGDBH												

EXHIBIT C-7

Search **Print****North Valley Division - Distribution (RT - 2017)****Work Request:** SHNV1023721**Contractor:** Davey Tree- Sent to Contractor.**Date Issued:** 4/5/2017 4:26:09 PM**Completed:** 4/12/2017 **By:** [REDACTED]

[REDACTED], IGO ... Circuit: GIRVAN 1101 - (0103401101)

1.) 2 Trim 2 Trim (TM) 4/12/17 **By:** [REDACTED] **r** *Invoiced*

[REDACTED], IGO ... Circuit: GIRVAN 1101 - (0103401101)

2.) 2 Trim 2 Trim (TM) 4/12/17 **By:** [REDACTED] **r** *Invoiced***Units Assigned: 4.0****Units Completed: 4.0 - (100.0%)****!** - Indicates that some of the work completed is different than what was assigned.**r** - Revised. Record has been billed and then updated by contractor.

PG&E Vegetation Management - VMS Database.

This Report was created on: 11/3/2020 3:58:21 PM.

EXHIBIT C-8

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A			City: IGO		County: SH	Directions: PLACER RD>W/ON SOUTH FORK RD>N/ON ZOGG MINE RD				Inspector / Company: [REDACTED] - CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 6091	SSD Rte #: 606060	Routing #: 299	(none):		Area:	SRA: Yes	Alerts: AX RP				
Insp Date / Time: 4/21/2017 10:30:16 AM		Tag Type:	Tag Number:	Line Name:		Pole Num:	Quad Map:	Removal #:	one: [REDACTED]				
Comment: P9 AP A/F PSTD ADD [REDACTED] ON GTE. TREE NXTO CRK @ GREEN GTE.													
									Audit		<i>Last Edit: 4/21/2017 1:06:44 PM by: [REDACTED]</i>		
Tree Number 1	Tree Species: Ponderosa Pine	Crew: CA	Priority: Routine	TGR: No	Owned By: Private	Height DBH 150 43	Clearance Prox: 95 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Major B	Account: E	Wire Conditions:	Insp Date: ([REDACTED]) 4/21/2017 10:40:47 AM
	Comment: .1S/E/OF P9 AP, X-RD					Notification: OK	Work Request: CENV1000581		WC Date: 5/3/2017	WC Qty: 1	WC Trim: FBB	Completed By: [REDACTED]	Invoice: BB (104)
	Lat/Long: 40.544285, -122.574228333 Google Map!					External TreeID:					Audit	Last Edit: 4/21/2017 1:06:44 PM by: [REDACTED]	
	Rx Comment: TBL, MAKE SAFE 4 LNS												

EXHIBIT C-9

Search **Print**

North Valley Division - Distribution (CM - 153400)

Work Request: CENV1000581

Contractor: Davey Tree- Sent to Contractor. **Order No:** 8176578

Date Issued: 4/24/2017 8:58:01 AM

Completed: 5/3/2017 **By:** [REDACTED]



Circuit: GIRVAN 1101 - (0103401101)

1.) 1 FP-Tr 1 FP-Tr 5/3/17 **By:** [REDACTED] r *Invoiced*

Units Assigned: 1.0

Units Completed: 1.0 - (100.0%)

! - Indicates that some of the work completed is different than what was assigned.
r - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 11/3/2020 3:57:53 PM.

EXHIBIT C-10

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

Address: [REDACTED]				City: IGO		County: SH		Directions: S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/O LARRY HORSE LN				Inspector / Company: [REDACTED] - CNU														
Division: North Valley		Circuit: (0103401101) GIRVAN 1101		SSD #: 3489		SSD Rte #: 50		Routing #: 861		(none):		Area: Q-25		SRA: Yes		Alerts: DG										
Insp Date / Time: (preload) 12/15/2017 1:22:42 PM			Tag Type:		Tag Number:		Line Name:			Pole Num:		Quad Map: C-6		Removal #: 3999214		Phone: [REDACTED]										
Comment: AX RED GATE @ PSTD ADD RIGHT @ FORK TO P8 TP ON DRWY PG&E LOCK																										
														Audit:		Last Edit: 12/15/2017 1:27:33 PM by: [REDACTED]										
Tree Number 0	Tree Species: Gray Pine		Crew: CA		Priority: Routine		TGR: No		Owned By: Private		Height DBH 45 22		Clearance Prox: 99 Inside		Cycle: Rtn		Qty: 1		Trim Type: FP-Rmv2 A		Account: M		Wire Conditions:		Insp Date: [REDACTED] 12/15/2017 1:22:42 PM	
	Comment: .3S/S/OF P8										Notification: OK		Work Request: SHNV1024631		WC Date: 1/2/2018		WC Qty: 1		WC Trim: F2B		Completed By: [REDACTED]		Invoice: B2 (104)			
	Lat/Long:							External TreeID:									Audit:		Last Edit: 12/15/2017 1:27:33 PM by: [REDACTED]							
	Rx Comment: CALL [REDACTED] IF QUESTIONS [REDACTED]																									

EXHIBIT C-11

Search | **Print**

North Valley Division - Distribution (RT - 147749)

Work Request: SHNV1024631

Contractor: Davey Tree- Sent to Contractor.

Date Issued: 12/18/2017 10:53:24 AM

Completed: 1/2/2018 **By:** 



Circuit: GIRVAN 1101 - (0103401101)

1.) 1 FP-R2 1 **FP-R2** ! 1/2/18 **By:**  *Invoiced*

Units Assigned: 1.0

Units Completed: 1.0 - (100.0%)

! - Indicates that some of the work completed is different than what was assigned.
r - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 12/28/2020 11:28:51 AM.

EXHIBIT C-12

Cust. Inf. | **MAP** | **History**

Inspection Record Detail

Address:				City: IGO		County: SH		Directions: WEST ON PLACER TO IGO>WEST ON SOUTH FORK ROAD>N/ON/ZOGG MINE ROAD				Inspector / Company: [REDACTED] - CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 4855	SSD Rte #: 50	Routing #: 9999				Area:	SRA No	Alerts:					
Insp Date / Time: 12/30/2019 11:31:39 AM		Tag Type: Unforeseen	Tag Number: 12302019	Line Name:			Pole Num:	Quad Map:	Removal #: 4048772		[REDACTED]				
Comment: TO POSTED ADDRESS; TREES UP HILL FROM P54 AND ACROSS STREET ; DUE BY 1-17-2020; PLEASE DO GOOD CLEANUP ; THANK YOU															
												<u>Audit</u>	<i>Last Edit: 12/30/2019 11:31:39 AM by: [REDACTED]</i>		
Tree Number 1	Tree Species: Ponderosa Pine	Crew: CA	Priority: Accelerate	TGR: No	Owned By: Private	Height 85	DBH 31	Clearance 99	Prox: Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Rmv3 B	Account: M	Wire Conditions:	Insp Date: ([REDACTED]) 12/30/2019 8:38:59 AM
	Comment: .6S/N/OF/P54; PINK PAINT					Notification: OK		Work Request: SHNV1028580		WC Date: 1/27/2020	WC Qty: 1	WC Trim: F3B	Completed By: SKYLINE A92	Invoice: XX (112)	
	Lat/Long: 40.536677, -122.558142 <u>Google Map!</u>				External TreeID: W122558142N40536677							<u>Audit</u>	Last Edit: 12/30/2019 8:44:01 AM by: [REDACTED]		
	Rx Comment: MIGHT BE LA; SCOUT FIRST; PLEASE COMPLETE BY 1-17-2020														
Tree Number 2	Tree Species: Canyon Live Oak	Crew: CA	Priority: Accelerate	TGR: No	Owned By: Private	Height 46	DBH 44	Clearance 14	Prox: Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Ov B	Account: M	Wire Conditions:	Insp Date: ([REDACTED]) 12/30/2019 8:42:16 AM
	Comment: .8S/N/OF/P54; PINK PAINT/FLAGGING					Notification: OK		Work Request: SHNV1028580		WC Date: 1/27/2020	WC Qty: 1	WC Trim: FOB	Completed By: SKYLINE A92	Invoice: XX (112)	
	Lat/Long: 40.53684, -122.558048 <u>Google Map!</u>				External TreeID: W122558048N40536840							<u>Audit</u>	Last Edit: 12/30/2019 11:20:30 AM by: [REDACTED]		
	Rx Comment: PLEASE COMPLETE BY 1-17-2020;														

EXHIBIT C-13

Search **Print****North Valley Division - Distribution (RT - 2019)****Work Request:** SHNV1028580**Contractor:** Wright Tree- Sent to Contractor.**Date Issued:** 12/31/2019 8:42:52 AM**Completed:** 5/12/2020 **By:** SKYLINE A92

		Circuit: GIRVAN 1101 - (0103401101)	
1.)	1 FP-R3	1 FP-R3 (Non-billable)	1/27/20 By: SKYLINE A92 r <i>Not Invoiced. (112)</i>
2.)	1 FP-Ov	1 FP-Ov (Non-billable)	1/27/20 By: SKYLINE A92 r <i>Not Invoiced. (112)</i>

Units Assigned: 2.0**Units Completed: 2.0 - (100.0%)**

! - Indicates that some of the work completed is different than what was assigned.
r - Revised. Record has been billed and then updated by contractor.



PG&E Vegetation Management - VMS Database.

This Report was created on: 11/3/2020 3:29:43 PM.

EXHIBIT C-14

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

A			City: IGO		County: SH	Directions: SW/ON PLACER>W/ON SOUTH FORK ROAD>N/ON/ZOGG MINE ROAD				Inspector / Company: CNU			
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 4191	SSD Rte #: 50	Routing #: 9999	(none):	Area:	SRA No	Alerts:					
Insp Date / Time: 4/21/2020 1:59:06 PM	Tag Type: Storm	Tag Number: HNP	Line Name:			Pole Num:	Quad Map:	Removal #:	Customer Name/Phone:				
Comment: P6 IS ROADSIDE NORTH OF POSTED ADDRESS ; TREE ON S/SD/RD/ FLGD PTD											<u>Audit</u> Last Edit 4/21/2020 4 57 24 PM by [REDACTED]		
Tree Number 1	Tree Species: Blue Oak	Crew: LA	Priority: No Trim	TGR: No	Owned By: Private	Height DBH 45 26	Clearance Prox: 12 Inside	Cycle: Rtn	Qty: 1	Trim Type: Side	Account: M	Wire Conditions:	Insp Date: (REDACTED) 4/21/2020 2:00:47 PM
	Comment: .1S/W/OF/P6; ROADSIDE; S/SD; FLGD/PTD					Notification: Inv	Work Request:	WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked	
	Lat/Long: 40.525423, -122.555645 <u>Google Map</u>				External TreeID: W122555645N40525423				<u>Audit</u>		Last Edit: 4/21/2020 4 55 21 PM by [REDACTED]		
	Rx Comment: **hn not issued, worked on Late PI**												

EXHIBIT C-15

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

Address:			City: IGO		County: SH	Directions: S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/OF LARRY HORSE LN			Inspector / Company: [REDACTED] - CNU				
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 4855	SSD Rte #: 50	Routing #: 1440	(none):		Area:	SRA No	Alerts:				
Insp Date / Time: 5/18/2020 10:58:41 AM		Tag Type: Unforeseen	Tag Number: HNP	Line Name:		Pole Num:	Quad Map:	Removal #: 4178869	Customer Name/Phone: [REDACTED]				
Comment: P64 4WAY ON DRWY @ PSTD ADD P1 1S/N/O P64 4WAY. STEEP DRWY! SMALL TA.													
									<u>Audit</u>		<i>Last Edit: 5/18/2020 4:43:35 PM by: [REDACTED]</i>		
Tree Number 1	Tree Species: Gray Pine	Crew: LA	Priority: No Trim	TGR: No	Owned By: Private	Height DBH 80 27	Clearance Prox: 99 Inside	Cycle: Rtn	Qty: 1	Trim Type: FP-Rmv3 B	Account: M	Wire Conditions:	Insp Date: ([REDACTED]) 5/18/2020 11:00:15 AM
	Comment: .7S/N/OF/P64 4 WAY; DEAD					Notification: Inv	Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked
	Lat/Long: 40.541343, -122.56507 Google Map!				External TreeID: W122565070N40541343					<u>Audit</u>		Last Edit: 5/18/2020 4:43:35 PM by: [REDACTED]	
	Rx Comment:												